

Direct Dial/Ext: 03000 414043

e-mail: Georgina.little@kent.gov.uk

Ask for: Georgina Little
Date: 18th September 2018

Dear Member

ENVIRONMENT & TRANSPORT CABINET COMMITTEE - THURSDAY, 20 SEPTEMBER 2018

I am now able to enclose, for consideration at next Thursday, 20 September 2018 meeting of the Environment & Transport Cabinet Committee, the following appendix which relates to Item 11 – Approach to Managing Highways Structures, which will replace the appendix (page78) in the printed agenda pack.

Agenda Item No

11 Approach to Managing Highway Structures (Pages 3 - 8)

To note the report and comment on the contents.

Yours sincerely

Benjamin Watts General Counsel



Appendix A A summary of substandard structures managed by Kent County Council [Highways Transportation & Waste]

Structure No.	Structure Name	Location	Category	Primary reason for sub-standard designation	Interim Measures
1	Ashford Town(W) N.Deck	Mace Lane, Ashford	Main Bridge > 3.0 m	Increased design and loading requirements since construction	Asset protection in place + 6 monthly monitoring
13	Bucksford	Chart Road, Ashford	Main Bridge > 3.0 m	Increased design and loading requirements since construction + deterioration	6 monthly monitoring
123	Worten Mill	Godinton Lane, Ashford	Main Bridge > 3.0 m	Increased design and loading requirements since construction	6 monthly monitoring
Page 3	Hampton	Hampton Park Road, Tonbridge	Main Bridge > 3.0 m	Deterioration	6 monthly monitoring
167	Old Blackmill Bridge	Old Mill Road, Canterbury	Main Bridge > 3.0 m	Increased design and loading requirements since construction	Closed to through traffic + 6 monthly monitoring
196	Stone Bridge	Front Road, Ashford	Minor Bridge 1.5 - 3.0 m	Increased design and loading requirements since construction	6 monthly monitoring
212	Stair	Old Hadlow Road, Tonbridge	Minor Bridge 1.5 - 3.0 m	Increased design and loading requirements since construction	6 monthly monitoring
216	Bow Bridge	Bow Bridge, Maidstone	Main Bridge > 3.0 m	Increased design and loading requirements since construction + deterioration	Structural weight limit imposed + 6 monthly monitoring in place
225	Jefferstone Lane	Jefferstone Lane, Folkestone and Htyhe	Main Bridge > 3.0 m	Inherited structure in poor condition	6 monthly monitoring

	226	Tonbridge Little	High Street, Tonbridge	Main Bridge > 3.0 m	Increased design and loading requirements since construction	6 monthly monitoring
	250	Chartham North	Station Road, Chartham	Main Bridge > 3.0 m	Increased design and loading requirements since construction	6 monthly monitoring
	262	Mayton Road	Mayton Lane, Canterbury	Minor Bridge 1.5 - 3.0 m	Increased design and loading requirements since construction	6 monthly monitoring
	320	Shalmsford Farm	Shalmsford Street, Canterbury	Main Bridge > 3.0 m	Deterioration	6 monthly monitoring
	324	Bolingbroke	Old Road, Thanet	Main Bridge > 3.0 m	Increased design and loading requirements since construction	6 monthly monitoring
Page	352	Ruckinge Canal	Marsh Road, Ashford	Main Bridge > 3.0 m	Increased design and loading requirements since construction	Structural weight limit imposed + 6 monthly monitoring in place
4	379	Kenardington No 1	Snargate Road, Ashford	Main Bridge > 3.0 m	Increased design and loading requirements since construction	Structural weight limit imposed + 6 monthly monitoring in place
	387	Bonnington No. One	Frogmore Lane, Ashford	Main Bridge > 3.0 m	Increased design and loading requirements since construction	Structural weight limit imposed + 6 monthly monitoring in place
	439	Grove Ferry	Grove Ferry Road, Canterbury	Main Bridge > 3.0 m	Increased design and loading requirements since construction + deterioration	Structural weight limit imposed + 6 monthly monitoring in place
	448	Arnolds Lodge	Seven Mile Lane, Tonbridge	Minor Bridge 1.5 - 3.0 m	Increased design and loading requirements since construction	6 monthly monitoring

	660	Sconce	Beckett Road, Folkestone and Hythe	Main Bridge > 3.0 m	Increased design and loading requirements since construction + Inherited structure in poor condition	6 monthly monitoring
	705	Hope Lane	Hope Lane, Folkestone and Hythe	Minor Bridge 1.5 - 3.0 m	Increased design and loading requirements since construction + Inherited structure in poor condition	6 monthly monitoring
	709	Yoakes	Wenham's Lane, Folkestone and Hythe	Main Bridge > 3.0 m	Increased design and loading requirements since construction + Inherited structure in poor condition	6 monthly monitoring
	723	Arrowhead	Arrowhead Lane, Folkestone and Hythe	Minor Bridge 1.5 - 3.0 m	Increased design and loading requirements since construction	Temporary overbridge installed + 6 monthly monitoring
Page	734	Grave Yard Bridge	Boarman's Lane, Folkestone and Hythe	Minor Bridge 1.5 - 3.0 m	Increased design and loading requirements since construction + Inherited structure in poor condition	6 monthly monitoring
ge 5	994	Stanford End	Hartfield Road, Sevenoaks	Minor Bridge 1.5 - 3.0 m	Deterioration	
	1020	Ashford Town(E) N.Deck	Mace Lane, Ashford	Main Bridge > 3.0 m	Increased design and loading requirements since construction	Asset protection in place + 6 monthly monitoring
	1058	Cattle Market Culvert	New Street, Sandwich	Minor Bridge 0.9 - 1.5 m	Historic designation - Strengthening works now completed - substandard designation is likely to be removed following review	
	1116	Bridge Farm North	Church Road, Ashford	Main Bridge > 3.0 m	Increased design and loading requirements since construction + Inherited structure in poor condition	6 monthly monitoring
	1445	Betenson Avenue	Betenson Avenue, Sevenoaks	Main Bridge > 3.0 m	Increased design and loading requirements since construction + deterioration	6 monthly monitoring

	1944	Austins Lane Culvert	Austins Lane, Sandwich	Minor Bridge 0.9 - 1.5 m	Increased design and loading requirements since construction + deterioration	6 monthly monitoring
	1945	Market Street Culvert	No Name Street, Sandwich	Minor Bridge 1.5 - 3.0 m	Increased design and loading requirements since construction + deterioration	6 monthly monitoring
	1946	Harnet Street Culvert	New Street, Sandwich	Minor Bridge 1.5 - 3.0 m	Historic designation - Strengthening works now completed - substandard designation is likely to be removed following review	
	2373	Star Inn	Lane from junction with Turnagate Cottage to Hope Lane, Folkestone and Hythe	Main Bridge > 3.0 m	Historic designation - Strengthening works now completed - substandard designation is likely to be removed following review	6 monthly monitoring
Page	2393	Turnpike Close	London Road, Hythe	Minor Bridge 1.5 - 3.0 m	Increased design and loading requirements since construction	6 monthly monitoring
-6-	3029	Cheriton Gardens Subway	Middelburg Square, Folkestone	Pedestrian Subway	Increased design and loading requirements since construction	6 monthly monitoring
	3120	Torrington Road	Rugby Gardens, Ashford	Main Bridge > 3.0 m	Increased design and loading requirements since construction + deterioration	Asset protection in place + 6 monthly monitoring
	3125	Mill Cottage	Mill Lane, Tonbridge	Main Bridge > 3.0 m	Increased design and loading requirements since construction + deterioration	6 monthly monitoring
	3168	The Causeway	Strand Street, Sandwich	Main Bridge > 3.0 m	Increased design and loading requirements since construction + deterioration	Structural weight limit imposed + 6 monthly monitoring in place

3649 Mill Street Bridge Street, Maidstone		Increased design and loading requirements since construction + deterioration	6 monthly monitoring
---	--	--	----------------------

This page is intentionally left blank