

Figure 1 – Cameras positioned at location 1.



Figure 3 – Camera positioned at location 3



Figure 2 – Cameras positioned at location 2



Figure 4 – Cameras positioned at location 4



Figure 5 – Cameras positioned at Location 5.



Figure 7 – Image taken from camera at location 1 directed at Brecon Chase access.



Figure 6 – Image taken from camera at location 1 directed at Brecon Chase access.




Figure 8 – Image taken from camera at location 3 directed at Brecon Chase pedestrian access.






Figure 9 – Image taken from camera at location 4 directed at Minster Road access and car park.



Figure 11 – Image taken from camera at location 5 directed towards the boundary with Bellevue Road.



Figure 10 – Image taken from camera at location 5 directed towards the playing field.

